

# DON'T GET HURT!

## STAY SAFE AT WORK


### Prevent falls

Always use 3 points of contact when getting on and off machinery.



### Power take-offs or PTOs are dangerous


Walk around PTOs, never jump over them. Don't wear loose clothing or drawstrings near PTOs.



Turn off power when connecting, disconnecting or servicing a machine.

### Protect your co-workers

Always look back when backing up. Do not permit others to ride.



### Prevent hearing loss

Wear hearing protection when working with noisy machinery.

### Seatbelts save lives

Always use a seatbelt on tractors and skid steers with rollover protection or ROPs.

