

DON'T GET HURT!

STAY SAFE AT WORK


Prevent falls

Always use 3 points of contact when getting on and off machinery.



Power take-offs or PTOs are dangerous


Walk around PTOs, never jump over them. Don't wear loose clothing or drawstrings near PTOs.



Turn off power when connecting, disconnecting or servicing a machine.

Protect your co-workers

Always look back when backing up. Do not permit others to ride.



Prevent hearing loss

Wear hearing protection when working with noisy machinery.

Seatbelts save lives

Always use a seatbelt on tractors and skid steers with rollover protection or ROPs.

